

SPRINT 382



Technical specifications



Power supply [Vac]	230
Absorbed power [W]	10
Max. Motor load [W]	1000
Max. accessories load [mA]	500
Operating ambient temperature	-20°C +55°C
Protective fuse	2
Function logics	Automatic/Automatic "Step by step" /Semi-automatic /Safety device/ Semi-automatic B/Manned C / Semi-automatic "Step by step"
Work time [sec]	Programmable (from 0 to 4 minutes)
Pause time [sec]	Programmable (from 0 to 4 minutes)
Thrust force	Adjustable on 50 levels
Terminal board inputs	Open/Open partial/Stop/Opening and closing safety device / Stop/Edge/Power supply + earth
Quick-fit connector	Opening and closing limit-switches/Encoder
Terminal board outputs	Blinker/Motor/Accessories power supply 24Vdc/ 24Vdc indicator light/Failsafe
Quick-fit connector	Genius 5PIN receivers
Programming	n° 3 keys (+, -, F) and display, simple or complete mode
Programmable functions in Simple mode	Function logic/ Pause time/Thrust force/ Gate direction
Programmable functions in Complete mode	Torque at start up/ Braking/Failsafe/Pre-flashing/ Indicator light/ Safety device logic /Encoder/Slow-downs/Partial opening time/ Work time/ Cycles counter for attendance request